





to re-draw the shapes for CNC programming. programming software. Shapes are irregular, so do not attempt Warning - Import dwg or dxf data directly into CNC

If in doubt, please ask Phil Saunders

Rev

Edition Scale Do not scale
Designed by PAS

Deutsche Schule

Solid-core laminate machining